

# WORKSHOP RECOMMENDATIONS



# WELDING RECOMMENDATIONS

SSAB's protection plates have a lean chemical composition which supports a high degree of weldability. Furthermore these steel grades can be welded by any conventional welding method. Suitable types of consumables cover ferritic and stainless types of consumables where the recommended types depend of the steel grade. All ArmoX grades can be welded to other weldable steels.

## EDGE PREPARATION

A good fit between the work pieces is essential to minimize stresses and thereby the risk of cracking. All types of impurities on and near the edges, such as mill scale, rust, oil, paint and moisture, etc. must be removed before welding.

## DEFINITION OF HEAT INPUT

Welding with recommended heat input results in good mechanical properties in the joint. The heat input (Q) from a welding performance depends of the current, voltage and travel speed and describes the delivered energy/length of the joint. Its' value affects the mechanical properties of the welded joint. During welding there is a loss of energy in the arc. The thermal efficiency factor [k] expresses the part of the heat input that is transferred to the joint. Different methods of welding have varying thermal efficiency. (k). See table below for approximate values of this property.

$$Q = \frac{k \times U \times I \times 60}{v \times 1000}$$

Q = Heat input [kJ/mm]      v = Welding speed [mm/min]  
 U = Voltage [V]              k = Thermal efficiency [dimensionless]  
 I = Current [A]

Picture 1 Heat input calculation

## TACK WELDING

During tack welding each tack weld is recommended to be minimum 50 mm long. The reason for this measure is to avoid hydrogen cracks in the joint.

## CARBON EQUIVALENTS FOR ARMOX

The resistance to hydrogen cracking for a steel can be expressed by the carbon equivalent for the steel. There are different types of carbon equivalents. The carbon equivalents according to CET and CEV are two of the most internationally common types. Low values of the carbon equivalents mean that less preheating temperatures of the joint is needed. Typical values for ArmoX can be seen in table 1.

Steel grade	Thickness range	CET <sup>1</sup> [%]	CEV <sup>1</sup> [%]
ArmoX 370T CL1 & CL2	3–100 mm	0.46–0.50	0.67–0.73
ArmoX 440T	4–80 mm	0.39–0.42	0.67–0.73
ArmoX 500T	3–80 mm	0.46–0.50 <sup>2</sup>	0.67–0.73 <sup>2</sup>
ArmoX 600T	4–20 mm	0.58–0.61	0.83–0.86
ArmoX Advance	4–12 mm	0.64–0.68	0.89–0.96

Table 1 <sup>1)</sup> Carbon equivalents, for calculations see picture 2. <sup>2)</sup> Valid for plate thicknesses up to 70 mm. Plate thicknesses 70.1–80 mm have typical CET values in the interval of 0.50–0.53 % and typical CEV values in the interval 0.73–0.93 %.

The definitions of the carbon equivalent CEV and CET are:

$$CET = C + \frac{Mn + Mo}{10} + \frac{Cr + Cu}{20} + \frac{Ni}{40}$$

$$CEV = C + \frac{Mn}{6} + \frac{Mo + Cr + V}{5} + \frac{Ni + Cu}{15}$$

Picture 2 Carbon equivalent calculation

## SELECTION OF WELDING CONSUMABLES

Ferritic and stainless types of consumables are recommended types of consumables. The possible types depend of the ArmoX grade and the plate thicknesses in the joint. The following issues applies for all types of consumables: In order to achieve an optimum combination of strength and toughness in the welded joint, select a consumable with as low strength as possible, but which still fulfils the strength requirements for the joint. Using low-strength consumables can offer several benefits, such as higher toughness of the weld metal, higher resistance to hydrogen cracking and lower residual stresses in the joint. Designers should therefore attempt to position the welds in low stress areas

## UNALLOYED AND LOW ALLOYED FERRITIC CONSUMABLES

If unalloyed- or low alloyed ferritic consumables are selected the suitable yield strength of these consumables are up to approximately 500 MPa. The recommended maximum hydrogen content of the consumables is 5ml/100 g of weld metal. Consumables for MAG welding with solid wire and TIG welding can fulfill this demand. For other welding methods, the following types of consumables have the possibility to meet the hydrogen attain the stated criteria:

- MAG welding with flux cored wires: Basic- and rutile types
- MAG welding with metal cored wires: Certain brand names
- SAW: Combinations of wire and basic flux

In the three last cases, exact hydrogen levels can for instance be found in the datasheet for the consumable.

## AUSTENITIC CONSUMABLES

The recommended austenitic consumables are according to type AWS 307 or AWS 309. We recommend giving first preference to consumables in accordance with AWS 307 and second preference to those in accordance with AWS 309. These types of consumables have yield strengths up to approximately 500 MPa in all the weld metal. Type AWS 307 can withstand hot cracking better than AWS 309. For stainless types of consumables no hydrogen specific maximum hydrogen criteria is stated. The reason is that hydrogen does not affect the performance as much as it does in unalloyed and low-alloyed consumables.

## HANDLING OF CONSUMABLES

If all types of consumables are stored in accordance with the manufacturer's recommendations, the hydrogen content will be maintained at the intended level. More information can be found in our TechSupport document regarding consumables. You find it under Downloads at [www.ssab.com](http://www.ssab.com), search for "consumables".

## PREHEAT TEMPERATURES

There are recommendations for both minimum and maximum preheat temperatures of the joint during a welding performance. The minimum preheat temperatures are requested in order to avoid hydrogen cracking. Maximum preheat temperatures on the other hand are set in order to avoid degradation of the mechanical properties in the whole welded structure. Preheat recommendations are found in table 2. The minimum preheat temperature depends of the steel grade, plate thickness in the joint, type of consumable and the heat input applied. If ferritic consumables are used preheating is always recommended.

## MINIMUM RECOMMENDED PREHEATING TEMPERATURES FOR DIFFERENT SINGLE PLATE THICKNESS (MM)

Ferretic consumables. Minimum recommended preheat for different plate thicknesses (mm).

	Thickness	3	10	20	30	40	50	60	70	80	90	100
Armox 370 T Class 1, Class 2	3-100 mm	50°C	100°C 125°C	150°C		175°C						
Armox 440 T	4-30 mm	50°C	75°C 125°C	150°C		175°C		200°C				
Armox 500 T	3-80 mm	50°C	100°C 125°C	150°C		175°C						

■ Only stainless steel consumables     Outside the size range

Austenitic consumables. Minimum recommended preheat for different plate thicknesses (mm).


	Thickness	3	10	20	30	40	50	60	70	80	90	100
Armox 370 T Class 1, Class 2	3-100 mm								100°C			
Armox 440 T	4-30 mm								100°C			
Armox 500 T	3-80 mm								100°C			
Armox 600 T	4-20 mm											
Armox advanced	4-12 mm	100°C										

■ Room temperature (approx. 20°C)     Outside the size range

**Table 2** The min preheat temperatures are applicable for heat inputs of 1,7kJ/mm or higher. Increase the minimum preheat temperature by 25°C in relation to the preheat table on the previous page for each of the following cases:

1. Welding of firmly clamped joints.
2. For heat inputs in the range of 1.0–1.6 kJ/mm. Contact SSAB for min preheat temperatures at low heat inputs below 1.0kJ/mm.
3. If the ambient humidity is high or the surrounding air- or joint temperature is below +5°C.


Room temperature refers to a temperature of the surrounding air and joint temperature of approximately 18°C–25°C. If this is not feasible temperatures down to +5°C in these areas can be accepted.




**Picture 3** Single and combined plate thicknesses

Maximum recommended preheat/interpass temperatures	
Armox 370 T Armox 370 T Class 2	400°C
Armox 440 T	200°C
Armox 500 T	200°C
Armox 600 T	180°C
Armox Advance	150°C

**Table 3** Max preheat temperatures



**Picture 4** Using preheating blankets.



**Picture 5** Performance of preheating



# CUTTING RECOMMENDATIONS

All high-hardness Armox plate (see the table below) should be cut under controlled conditions as described below:

Armox 370T CL1 & CL2	Armox 440	Armox 500T	Armox 600T	Armox Advance	Recommended cutting method
Up to 15 mm	Up to 25 mm	Up to 15 mm	Up to 10 mm	NA	<ul style="list-style-type: none"> <li>• Abrasive waterjet</li> <li>• Plasma</li> <li>• Laser</li> <li>• Abrasive disc</li> </ul>
15–25 mm	25–30 mm	15–25 mm	10–20 mm	NA	<ul style="list-style-type: none"> <li>• Abrasive waterjet</li> <li>• Laser</li> <li>• Gas cutting at reduced speed</li> <li>• Gas cutting plus preheating to <math>170 \pm 30^\circ\text{C}</math></li> <li>• Abrasive disc</li> </ul>
40–60 mm	25–30 mm	40–60 mm	NA	NA	<ul style="list-style-type: none"> <li>• Abrasive waterjet</li> <li>• Gas cutting plus preheating to <math>170 \pm 30^\circ\text{C}</math> plus keep warm for 4 hours at <math>160 \pm 40^\circ\text{C}</math></li> <li>• Abrasive disc</li> </ul>
Above 60 mm	NA	Above 60 mm	NA	Up to 12 mm	<ul style="list-style-type: none"> <li>• Abrasive waterjet</li> <li>• Abrasive disc</li> </ul>

**Table 4** Preferred cutting methods.

## ABRASIVE WATERJET

This process can be applied to all of the Armox plates and is the preferred method, because the absence of HAZ eliminates the risk of cracking.

## LASER CUTTING

Armox Advanced and Armox 600T up to around 20 mm thick can be cut using this process. It generates a narrow kerf, usually less than 1 mm, and a narrow HAZ, usually less than 3 mm.

## PLASMA CUTTING

Armox Advanced and Armox 600T up to around 25 mm thick can be cut using this process. It generates a kerf, usually 3–4 mm, and a HAZ up to 5 mm. Plasma cutting can be performed under water, which minimizes the amount of distortion and generates a more narrow HAZ.

## GAS CUTTING

This process can be applied to Armox plates up to 60 mm thick, see details in table 6. It generates a kerf of 2–5 mm and a HAZ which is usually 4–10 mm wide.

Uncontrolled gas cutting of high-hardness armour plate may result in hydrogen cracking (also called cold cracking) which may occur in thicknesses above 20–30 mm. The thicker the plate, the higher the sensitivity to cracking.

The most effective technique for avoiding cracking during and after the cutting process is to pre-heat the plate and then keep the cut parts at an elevated temperature as can be seen in table 4.

Preheating consists of bringing the whole plate, or at least a 100 mm wide area on either side of the future kerf, up to a specified minimum temperature before the process begins. This can be done by using thermostatically controlled furnaces, heating blankets or, in some cases, using gas burners to maintain the temperature throughout the process.

The same equipment can be used to keep the parts at keep the cut parts at an elevated temperature as can be seen in table 6. Reduced cutting speed is possible only when the cut parts are wide enough to consume the excessive heat. If in doubt contact SSAB.

## ABRASIVE DISC

This process is usually applied to the cutting of tube and rod but can also be adopted for straight line cutting of the complete range of high-hardness Armox plate. The kerf is the thickness of the disc, with little or no HAZ.




Abrasive waterjet



Laser cutting



Plasma cutting



Gas cutting

# MACHINING RECOMMENDATIONS

Drilling can be performed using high-speed steel drills or cemented carbide drills, when drilling in Armox with HSS drills in radial/column drilling machines is the first choice a HSS-Co 8% drill with a small helix angel, for individual holes you can use an ordinary HSS drill.

## Advice for reducing vibrations and increasing the lifetime on the drill:

- Minimize the distances to the column and between to drill tip and the workpiece.
- Don't use longer drill than necessary
- Always use metal supports.
- Clamp securely
- Solid and firm table
- Use coolant
- Just before the drill breaks through, disengage the feed rate for about a second, play/spring back can otherwise snap the drill tip, Re-engage the feed rate when the play/spring back have ceased.



## HSS-drill



	Armox 370T CL1 & CL2	Armox 440T	Armox 500T
$V_c$ [m/min]	~ 9	~ 7	~ 5
$D_c$ [mm]	Feed rate [mm/rev] and speed [RPM]		
5	0.05 / 575	0.05 / 445	0.05 / 320
10	0.10 / 285	0.09 / 220	0.08 / 130
20	0.23 / 145	0.20 / 110	0.18 / 65
30	0.35 / 95	0.30 / 75	0.25 / 45

Table 5

## DRILLING RECOMMENDATIONS WHEN THE MACHINE CONDITIONS IS GOOD



## Solid cemented carbide drill

	Armox 370T CL1 & CL2	Armox 440T	Armox 500T	Armox 600T	Armox Advance
Cutting speed, $V_c$ [m/min]	35–45	30–40	25–35	20–30	18–25
Feed rate, $f_n$ [mm/rev]	0.1–0.15	0.1–0.15	0.08–0.12	0.06–0.1	0,08–0,10

Table 6



## Exchangeable-tip drill

	Armox 370T CL1 & CL2	Armox 440T	Armox 500T	Armox 600T
Cutting speed, $V_c$ [m/min]	35–45	30–40	20–30	20–30
Feed rate, $f_n$ [mm/rev]	0.10–0.15	0.1–0.15	0.08–0.12	0.07–0.12

Table 7



## Indexable insert drill

	Armox 370T CL1 & CL2	Armox 440T	Armox 500T	Armox 600T
Cutting speed, $V_c$ [m/min]	60–80	50–70	40–60	30–40
Feed rate, $f_n$ [mm/rev]	0.06–0.14	0.06–0.14	0.06–0.12	0.05–0.1

Table 8

## COUNTERSINKING AND COUNTERBORING

Countersinking/boring are best performed using tools which have replaceable inserts. Always use a revolving pilot and use coolant.



	Armox 370T CL1 & CL2	Armox 440T	Armox 500T	Armox 600T
$V_c$ [m/min]	25–70	20–50	17–50	12–40
Feed rate [mm/rev]	0.10–0.20	0.10–0.20	0.10–0.20	0.10–0.20
$D_c$ [mm]	Speed [RPM]			
19	420–1175	335–840	285–840	201–670
24	330–930	265–665	225–665	151–531
34	235–655	185–470	160–470	112–375
42	190–530	150–380	130–380	91–303
57	140–390	110–280	95–280	67–223

**Table 9** \* Reduce the cutting data with about 30 % in countersinking.

## TAPPING/THREAD MILLING

With the correct tools can all tapping/thread milling be performed in all Armox grades. We recommend four-flute taps which can withstand very high torque which occurs during tapping in hard materials. If the strength not is critical, the drilled hole can be 3% larger than standard, that will increase the lifetime on the tap.

	Armox 370T CL1 & CL2	Armox 440T	Armox 500T
$V_c$ [m/min]	~ 5	~ 3	~ 2.5
$D_c$ [mm]	Feed rate [mm/rev] and speed [RPM]		
M 5	320	-	-
M10	160	95	80
M16	100	60	50
M20	80	50	40
M24	65	40	30
M30	55	30	25



**Table 10** - Tapping is not suitable we recommend thread milling.

## SOLID CEMENTED THREAD MILL

	Armox 370T CL1 & CL2	Armox 440T	Armox 500T	Armox 600T	Armox Advance
	Cutting speed $V_c$ [m/min] and feed rate [mm/rev]				
$V_c$	60–80	50–70	40–60	30–40	25–35
$f_n$	0.02–0.05	0.02–0.05	0.02–0.05	0.01–0.03	0.01–0.03

**Table 11** \* To manage thread milling, a CNC machine with minimum 3-axis is necessary and the thread should be made in 2 passes.



## MILLING

To ensure rational production, milling cutters with cemented carbide inserts are recommended.




FACE MILLING		
<b>Grade</b>	P30 / C6	P20-P30 / C6-C7
<b>Conditions</b>	average	stable
<b>Feed rate [fz]</b>	0.1–0.2–0.3	0.1–0.2
Cutting speed, $V_c$ [m/min]		
<b>Armox 370T CL1 &amp; CL2</b>	150–120–110	150–120
<b>Armox 440T</b>	150–120–110	150–120
<b>Armox 500T</b>	120–100	120–100
<b>Armox 500T</b>	120–100	120–100
<b>Armox 600T</b>	-	* 70–50
<b>Armox Advance</b>	-	* 50–35

**Table 12** \* fz recommendation 0.07–0.12

### Keep this in mind:

- Position the cutter off-centre (to the left) to achieve a thicker chip at the entry and to avoid thick chip on the exit.
- Cutter diameter should be 20%-50% larger than the width of cut, ae.
- Avoid to center the cutter on centre line that will generate more of vibrations.
- Always use down milling (climb milling).




	CC	
<b>Grade</b>	P30 / C6	insert
<b>Conditions</b>	coated	stable
<b>Feed rate [fz]</b>	0.02–0.20	0.05–0.15
Cutting speed, $V_c$ [m/min]		
<b>Armox 370T CL1 &amp; CL2</b>	100	110–90
<b>Armox 440T</b>	100	110–90
<b>Armox 500T</b>	80	90–70
<b>Armox 600</b>	-	-
<b>Armox Advance</b>	-	-

**Table 13**



# BENDING RECOMMENDATIONS

This section deals with free bending, although roll bending or folding can also be employed. The bending results are dependent on a number of factors, which we have grouped under three headings: the plate, the tools and the procedure. Typical physical properties of the materials are given in the table below.



**Picture 6** Minimum recommended punch radius (R) and die opening width (W) for plate thickness (t) when the plate is bent to 90° parallel to the final rolling direction and transverse to the final direction of rolling – and also the corresponding springback.

## Bending transverse to the final direction of rolling

- Bending at right angles to the rolling direction
- Grind away any blemishes before bending
- Sheared edges should also be grinded

The identity of the plate is always stamped across the rolling direction. Avoid placing the plate so that the stamping occurs in the bend line, due to the risk of cracking. The edges of the die opening should always be as hard as or harder than the plate being bent, in order to avoid damage to the die.

A simple way of achieving this is to mill grooves in the die edges and fit lubricated rods of hardened tool steel into the grooves. The edge radius of the die should be at least half the plate thickness. The die opening angle must allow for spring back of the plate without bottoming out in the tool. As an example, if ArmoX 500 is to be bent to an angle of 90°, the die opening angle should not be greater than 70° ( see Table 1).

	Hardness [HBW]	Tensile strength $R_m$ [MPa]	Elongation $A_5$ [%]
S 355 acc to EN10025	180	550	28
<b>Armox 370T CL1 &amp; CL2</b>	380–430	1200	11
<b>Armox 440</b>	420–480	1400	10
<b>Armox 500T</b>	480–540	1600	8
<b>Armox 600T</b>	570–640	2000	7
<b>Armox Advance</b>	58–63 HRC	>2000	>7

**Table 14** Care should be taken during all bending – due to the high strength of the plate and the high bending force necessary.

The results of a bending operation are affected by the plate, the tools and the procedure employed:

## THE PLATE

### Steel grade

Note that the bending force and spring back increase with the plate strength. (For typical tensile strength values, see table 16.)

Harder plate:

- increased bending force
- increased spring back
- larger top tool radius

### Plate surface

Our recommendations apply to shot blasted and anti-corrosion painted plate. Surface damage and rust which is under tension during bending may greatly reduce the bendability. In critical cases, such defects can often be removed with careful grinding. Grinding scratches shall preferably be placed perpendicular to the bend line.

### Plate edges

Cut and sheared edges should be deburred and rounded with a grinder.

### Direction of rolling of the plate

The plate can be bent to a smaller radius at right angles to the direction of rolling than in the direction of rolling. See Figure 1 and table below.


### Bend length (b)

If the bend length is less than 10 times the plate thickness, the plate can often be bent to a smaller radius than the values given in table below.

## THE TOOLS

### Punch radius (R)

The correct punch radius, along with the die width, is the most important parameter when bending Armox (See Table 2). When bending high strength steel, the final inner radius often becomes somewhat smaller than the radius of the punch, see figure below. When there is low friction between plate and tools, the phenomenon becomes more obvious.



**Picture 7** Separation on the plate during bending.

	Thickness [mm]	At right angles R/t	Along R/t	At right angles W/t	Along W/t	Springback [°]
Armox 370T CL1 & CL2	t<8	3.0	3.5	9	10.5	9–13
	8–15	4.0	5.0	10	11	
	>–15	5.0	6.0	12	13	
Armox 440	t<8	4.0	4.0	10	10	11–18
	8–15	4.0	4.0	10	12	
	>–15	4.5	5.0	12	14	
Armox 500T	t<8	4.0	4.0	10	12	12–20
	8–15	4.0	4.0	12	14	
	>–15	5.5	6.0	16	18	
Armox 600T	Contact SSAB					
Advance	Contact SSAB					

**Table 15** The minimum recommended punch radius (R) and die opening width (W) for plate thickness (t) when the plate is being bent to 90° along the direction of rolling and at right angles to the direction of rolling – and also the corresponding spring back.

Care should be taken during all bending – due to the high strength of the plate and the high bending force necessary. If the plate should crack, fragments of the material may fly off. During bending, the operator and other personnel must therefore not stand in front of the machine – they should move to the side.

## THE TOOLS (CONT'D)

### Die opening width (W)

Table 16 specifies the minimum recommended die opening. If the width is increased, the bending force and impression marks will admittedly be reduced, but at the expense of increased spring back.

Note that the opening angle must be so small that it will allow a sufficient amount of over-bending. (See picture 6 and table 16.) In roll bending, the spring back will be much larger than the tabulated values.

## BENDING PROCEDURE

### Friction

The die edges must be clean and undamaged. The bending force needed and the risk of cracking can be reduced by using round rods free to rotate as die edges and/or by lubricating the die edges.

### Bending angle

The recommendations in table 16 relates to bending to an angle of 90 degrees. Note that the bending angle has a lesser effect on the force needed and the spring back than the die opening width and steel grade. Spring back can be compensated by over-bending by the same number of degrees.

### Bending force (P)

To make an estimation of the force needed during bending, we pay attention not only to the bend length, plate thickness, die width and tensile strength, but also the changing moment arm during bending. The peak load is assumed to be reached at a bend opening angle of 120° with normal friction (no lubrication). Trial tests are always recommended.

$$P = \frac{b \cdot t^2 \cdot R_m}{(W - R_d - R_p) \cdot 9\,800}$$

P = Bend force, tons (metric)  
t = Plate thickness, mm  
W = Die width, mm (figure 1)  
b = Bend length, mm

R<sub>m</sub> = Tensile strength, MPa (table 1)  
R<sub>d</sub> = Die entry radius, mm  
R<sub>p</sub> = Punch radius, mm

### Picture 8

## DIE WIDTH

Spring back increases with increased die width, while punch force is reduced. Make sure that the opening angle of the die allows for over-bending without bottoming out, to compensate for spring back. An increased die opening width can in many cases lower the strain level in the bend. Also, make sure that there is enough room for the chosen punch together with the workpiece, in the die, during bending, without deforming the die. The minimum recommended die opening width are shown in table 16.

The die should preferably be equipped with round lubricated rods of hardened tool steel as mentioned earlier. If the die doesn't have rollers, the die edge radius should be at least half the plate thickness. Alternatively, the die width should be increased in order to minimize pressure on the die edge radius, and consequently reduce the risk of die marks. To avoid excessive tool wear, tooling should be harder than the work piece.

SSAB is a Nordic and US-based steel company. SSAB offers value added products and services developed in close cooperation with its customers to create a stronger, lighter and more sustainable world. SSAB has employees in over 50 countries. SSAB has production facilities in Sweden, Finland and the US. SSAB is listed on the Nasdaq OMX Nordic Exchange in Stockholm and has a secondary listing on the Nasdaq OMX in Helsinki.

SSAB  
SE-613 80 Oxelösund  
Sweden

T +46 155 25 40 00  
F +46 155 25 40 73  
contact@ssab.com

[www.ssab.com](http://www.ssab.com)

This leaflet contains general suggestions and calculation models. SSAB Oxelösund AB does hereby expressly exclude any liability whatsoever for their suitability for individual applications. It is the responsibility of the user of the manual to adapt the recommendations contained herein to the requirements of individual applications.

701-en-Armox: WORKSHOP RECOMMENDATIONS-V1\_2019\_ [www.solodesign.se](http://www.solodesign.se) Österbergs tryckeri.

**SSAB**